MATERIAL SAFETY DATA SHEET

SECTION I – PRODUCT IDENTIFICATION

Company Name:	Danville Materials
	2021 Omega Road
	San Ramon, CA 94583
Phone:	(800) 822-9294
Fax:	(925) 838-0944
Prepared:	September 22, 2003

SECTION II – HAZARDOUS INGREDIENTS OF MIXTURES

Hazardous Component	OSHA PEL	ACGIH TLV
Barium Glass	15	10
BIS GMA	ND	ND
Amorphous Silica	ND	ND

SECTION III – PHYSICAL DATA

(ND) = Not Determined NA = Not Applicable NL = Not Listed

Vapor Pressure mm HG: ND
Vapor Density (Air = 1): NA
Evaporation Rate (Ether = 1): NA
% Volatile by volume: NA
Solubility in H20: Insoluble
Boiling Point: ND
Appearance: Tooth-Shaded Resin Paste
Odor: Slight
Specific Gravity (H2 = 1): > 1

SECTION IV – FIRE AND EXPLOSION

Flash Point: > + 104 deg. F
Extinguishing Media: Carbon Dioxide, foam, dry chemical
Special Fire-Fighting Procedures: None
Flammable Limits: ND
Unusual Fire and Explosion Hazards: None

SECTION V – REACTIVITY DATA

Stability: Unstable ( ) Stable (X)
Conditions to avoid: Prolonged extreme heat beyond 40 deg. C, and intense light.
Incompatibility: ND
Hazardous Decomposition Products: None known
Hazardous Polymerization: May occur ( ) Will not occur (X) None

SECTION VI – HEALTH HAZARDS

OSHA Permissible Exposure Limits: None
Other Exposure Limit Used: None
ACGIH Threshold Exposure Limit: None

Chronic, Other: None
Acute Overexposure: Irritation to eyes and skin may occur with uncured resins. May cause skin sensitivity in select individuals.
Medical Conditions generally aggravated by exposure: None known
Hygienic Practices: None
Primary Route(s) of Exposure: Skin: Yes. Inhalation and ingestion: No

SECTION VII – EMERGENCY AND FIRST AID PROCEDURES
Signs of Exposure: Severe skin or eye irritation, redness or burning sensation.
Skin: Wash off affected area with soap and water.
Ingestion: Seek immediate medical advice, carry container with label.
Eyes: Rinse immediately with plenty of water and seek medical advice.

SECTION VIII– SAFE HANDLING & USE PRECAUTIONS
Spill Management: Use absorbent to collect the material. Wash contaminated surfaces with soap and water.
Waste Disposal Methods: This material contains hazardous constituents. Dispose of safely in accordance with local, state, and federal regulations. Avoid temperatures in excess of 40 deg. C.

SECTION IX – PROTECTION INFORMATION/CONTROL MEASURES
Respiratory: None
Eye Protection: Safety goggles
Gloves: Surgical rubber/PVC gloves
Other Clothing & Equipment: Face Mask
Ventilation: None required, local exhaust recommended.

DANVILLE MATERIALS
2021 OMEGA ROAD SAN RAMON, CALIFORNIA 94583 USA
PHONE 800/822-9294 FAX 925/838-0944